


BIKE	HONDA VTR 1000 FIRESTORM	PART NO.	EHA - 55
YEAR	1997 - 2004	FIT KITS	OVAL Z039.11047 // ROUND Z039.10047
NOTES	Where not supplied use original fittings	FEATURES	DB KILLER Z038.10120



- | | |
|--|---|
| 1 2 x 450mm Silencers ESC 50 | 8 2 x Aluminium Bolt Finishers (Z026.20068) |
| 2 2 x 51-55mm Band Clamps (Z016.10002) | 9 Connecting Pipe CP7 |
| 3 4 x M8 x 17mm Washers (Z017.10831) | 10 Connecting Pipe CP8 |
| 4 2 x 10mm Aluminium Spacers (Z026.10004) | 11 2 x 43-47mm Band Clamps (Z016.10008) |
| 5 2 x M8 Lock Nuts (Z017.10062) | 12 4 x 8 x 25mm Washers (Z017.10825) |
| 6 2 x M8 x 60mm Cap Head Bolts (Z017.10080) | 13 2 x Bump Stop Kits (Z017.10010) |
| 7 2 x Comp Silencer Straps (R-Z038.10090) (O-Z038.10088) | |

E-MARK ROUND	SCDB-RS e4 2035
E-MARK OVAL	SCDB-OS e4 2072
ISSUE NO.	7
DATE	24/12/08
AUTHORISED	S.Northrop
CHECKED	

NOTE: ENSURE SCORPION SYSTEM IS CLEAR OF MOVING PARTS AND ALL ORIGINAL FUNCTIONS WORK CORRECTLY.

A) Remove original exhaust from bike, taking care to keep all original components in a safe place.

B) Refit Scorpion exhaust as per line diagram above.

C) When fitted take bike for a short ride to ensure all functions are correct.

D) When bike & exhaust are cool enough check all nuts and bolts are still secure.