





HUSQVARNA VITPILEN 401



*Racing configuration

Test conditions:

997 mBar
19 °C

Reference conditions:

1013 mBar
20 °C